


USER MANUAL



Load
250 Kg / 580 lbs
Mil Std
stripes




Make sure red stripes location under armpit & knees

Place casualty head on upper net

Place casualty bottom on lower net

Use the 4 red stripes as main handles. Additional 4 black stripes (with TREETAC logo in red) can be used for additional support

Make sure correct grip



2-4 users carrying with red handles, remaining marked handles for support



TRN - CARE & MAINTENANCE

CLEANING YOUR TRN

The TRN is a specially designated one-time use device, however the TRN is extremely durable and can be easily cleaned and reused as long as it's free of any defects.

CLEANING INSTRUCTIONS

1. The TRN can be easily cleaned manually with lukewarm water and mild soap.
2. A bathtub or large pail works well to allow complete submersion.
3. Make sure to wipe off excess soap and ensure the TRN is completely dry
4. Make sure to close all Velcro fasteners before cleaning.
5. Machine washing is possible but less recommended and can cause paint removal and wear.
6. Use low-suds detergent, according to detergent manufacturer's directions – if a detergent is harmful to your skin then it is harmful to your TRN.
7. Place the TRN on a hanger and allow to air dry indoors.

Additional instructions:

- Do not clean if not essential.
- Do not use bleach or bleach substitutes.
- Do not use dryer.
- Do not expose the TRN to any petroleum, chemical, chlorine products, corrosive materials such as battery acid, battery fumes, solvents, antifreeze or isopropyl alcohol. Long exposure to such agents can result in decrease of performance.

STORAGE OF THE TRN

When you are not using the TRN, it should be stored under normal environmental conditions (room temperature).

The resistance and performance of textile can change with time and wear, especially when exposed to extreme environmental conditions. The TRN although extremely durable should not be stored in places where it is exposed to high temperatures and high humidity for long periods of time.

INSPECTION & RETIREMENT

- Inspect the TRN for signs of damage and wear before and after each use.
- Damaged gear must be retired and destroyed to prevent future use. Retire immediately if: There is a rip or hole in the webbing. If the webbing is burnt, singed or melted. There are any torn threads or heavy abrasion to the webbing or bar tacks. The webbing is faded due to exposure to sunlight. Factors that reduce the lifespan: Falls, abrasion, wear, prolonged exposure to sunlight, salt water/air or harsh environments.
- If you have any doubts about the dependability of your TRN, retire it.

CONTACT US

Our mission is to protect and enhance lives. We are committed to provide the highest level of service. Please contact us for any question or concern Via Email: info@treetac.com or through TreeTac's web site: www.treetac.com